



ISTITUTO SERVIZI
EUROPEI TECNOLOGICI

ISET S.r.l.

Sede Legale e Uffici
Via Donatori di sangue, 9 - 46024 Moglia (MN)
Tel. e fax +39 (0)376 598963
iset@iset-italia.com www.iset-italia.eu

Cap. soc. i.v. € 10.200,00
Cod. Fisc. e P.IVA 02 332 750 369
Reg. Imprese 02 332 750 369
REA MN 0221098

CERTIFICATE OF COMPLIANCE

Certificado de Conformidade - Сертификат соответствия - Konformitätserklärung

1) APPLICANT:

INDUSTRONIC
Miguel Aleman B7, Col. Jardines de la Victoria,
67119 Guadalupe, Nuevo Leon, Mexico

MANUFACTURER:

NORTEC SA DE CV
Miguel Aleman B7, Col. Jardines de la Victoria,
67119 Guadalupe, Nuevo Leon, Mexico

2) CERTIFICATE NO.:

IT091041NT170323

TCF(S) NO.:

TCF(17)-UPS2017031001a

3) WITH REFERENCE TO EC DIRECTIVE APPLIED:

Low Voltage Directive 2014/35/EU
Electromagnetic Compatibility 2014/30/EU

HARMONIZED STANDARDS APPLIED:

EN 62040-1:2008/A1:2013/AC:2009,
EN 62040-2:2006/AC:2006

4) CERTIFICATION ISET MARK:



5) PRODUCT CHARACTERISTICS: Uninterruptable Power Systems(UPS)

MODEL(S): UPS-IND 13600,UPS-IND 1310,UPS-IND 1315,UPS-IND 1320,UPS-IND 1330,UPS-IND 1340,
UPS-IND 1350,UPS-IND 1360,UPS-IND 1380,UPS-IND 13100,UPS-IND 13120,UPS-IND 13160,
UPS-IND 13200,UPS-IND 13250,UPS-IND 13300,UPS-IND 13400,UPS-IND 13500

REMARK: The verification has been carried out on voluntary application of the manufacturer based only on the documents prepared and provided by the manufacturer itself. The product(s) satisfies the requirements of the Certification Mark of ISET according to the ISET regulations. The manufacturer is responsible to maintain the internal production control to ensure the compliance of the product. ISET declines any liability with reference to any other noncompliance of documents, product or test report that have been submitted to evaluation. However CE marking and EC declaration are duties of the manufacturer before putting into service of its product(s) on market as well as the verification doesn't imply assessment of the production of the product(s). The manufacturer is liable to take all the necessary actions required by the applicable directives&procedures before putting CE mark on the product(s). The manufacturer should be responsible for the results caused by improperly use this verification.

6) DATE OF ISSUE: 23/03/2017

CERTIFICATION MANAGER:

